



ESSENTIAL JOB ELEMENTS - SHEETMETAL WORKER FIELD

RESPONSIBILITIES:

1. Measure, assemble, and install sheet metal according to job specifications.
2. Plans sequence of installation and activities of apprentices, helpers, and laborers.
3. Sets up and operates welding equipment. (Not for all jobs.)
4. Inspects assemblies according to job specifications.
5. Insulate work as necessary.
6. Follows safe work practices.
7. Maintains clean and orderly work area.

EXPERIENCE:

1. Four (4) years job experience, completion of apprenticeship program or other industry-recognized experience.
2. Operate lifting equipment, punch and drill presses, welding equipment, and measuring instruments.
3. Read blueprints, drawings, and job specifications.
4. Stick, Mig, and Tig weld per job requirements.

PHYSICAL QUALIFICATIONS:

1. Commercial Drivers License (not applicable to all positions).
2. Climb up or down ladders, stairs, scaffolds.
3. Maintain balance on scaffolding and platforms.
4. Reach for, handle and manipulate objects and material.
5. Lift and carry objects up to 100 pounds.
6. Stoop, kneel, crouch, and crawl.
7. Stand and walk for long periods.
8. See and hear (either naturally or with correction).
9. Work in pits, ditches, and elevated areas.

Please review this copy of the essential elements for the job position. Are you aware of any reasons you cannot perform the essential elements of the job? _____